

Web Inquiry
Assigned to individual

Control Number	DBON-9CWHCM
Type of Inquiry	<input checked="" type="radio"/> Normal <input type="radio"/> Urgent
Assigned To	Wanda Calderon 212-637-3668
Assigned To Org	PAD-POB
Assigned Date	10/28/2013
Due Date	11/04/2013
Status	Assigned to individual
Days since delivered	18
Days since assigned	15
Comments	This is a FOIA request

There are no responses [Respond Now](#)

From	"Jonquile Williams" <jwilliams@bestinspections.com>
Delivered Date	10/25/2013 12:58 PM
Subject	FW: Information Request

From: Jonquile Williams [mailto:jwilliams@bestinspections.com]
Sent: Friday, October 25, 2013 12:58 PM
To: 'R2_Web_Inquiry@epamail.epa.gov.'
Subject: Information Request

This email is in regards to an ongoing environmental site assessment for the Anthos at Kirkwood and in doing so I would like to request information regarding the adjoining property etc. attached is a formal request.

If there is a fee for this request please inform me prior to any research done

Thank you

Jonquile T. Williams
Environmental Analyst
Building Evaluation Services and Technology
5115 Pegasus Court, Suite F
Frederick, Maryland 21704
Phone: 301-972-4660
Fax: 240-629-8171



Anthos at Kirkwood FOIA.pdf

Log

BUILDING EVALUATION SERVICES AND TECHNOLOGY

Date: October 25, 2013
To: EPA Region 2
Subject: Request for Information
Reference: Anthos at Kirkwood (BEST Job# 13-330)
913-923 & 931 Route 11
Kirkwood NY 13795

Dear EPA Region 2

Building Evaluation Services and Technology is a consulting firm working with the owners of the referenced property, or a property manager for financing of the referenced property, to obtain information on the referenced property and to conduct a review of current and historical conditions that could potentially impact or impair the condition of this property. Through the Freedom of Information Act, we respectfully request the following information and records in regards to the referenced property:

An adjoining property currently the River Run II Golf Course listed on a hazardous waste site database as the former facility "Gorick Dump." In the facility explanation for the Gorick Dump it's mentioned that there was off-site ground water contamination including the Town of Kirkwood Municipal Well #1 and well #3. Since these wells provide drinking water to the Town of Kirkwood including the Anthos at Kirkwood property, I would like to request records regarding the former Gorick Dump facility that include the following:


- When did the landfill open, when did it close
- What was disposed of in the landfill
- Sampling reports, along with any maps of where the samples were taken, any monitoring wells etc.
- Who is the responsible party for cleanup and possible remediation
- What is the current status of the cleanup of the landfill
- What kind of remediation methods are they pursuing (i.e. are they capping it? quarterly monitoring? Etc.) and when can they be expected to be completed.
- Is there a threat to human health or the environment from this landfill.



BUILDING EVALUATION SERVICES AND TECHNOLOGY

Please include **Project # 13-330** on all correspondence forwarded to our office. **Please notify our office if a fee of any kind is necessary to fulfill this request before any work is done.** Building Evaluation Services and Technology appreciates your efforts in responding to this request. Should you have questions or concerns in this matter or require additional data, please contact me at (301) 972-4660 or fax (240) 629-8171.

Respectfully,



Jonquile T. Williams
Environmental Analyst

Helping Lenders Understand Complex Building Issues

5115 Pegasus Court, Suite F • Frederick, Maryland 21704
301/972-4660 • 888/972-4660 • FAX 240/629-8171

